Inspection Summary

Permit #:PRPWTC20253760, PW Temporary Traffic Control Permit
Address: 10 NE TUDOR RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Eric Wiggins	Passed	Friday, March 13, 2026

Corrective Action Required

1	Misc	Site visit. Both the east and west lanes were both closed at the same time. I spoke to the contractor he was aware of their mistake and is will be having at least one of the lanes back open as soon as possible. I will continue to monitor.

Corrective Action Required

2	Misc	Site visit. While I was driving down Douglas Rd I noticed that the TTC was set up on Tudor Rd east of Douglas, but not on Tudor Rd on the west side of Douglas, with no work being done on Tudor Rd. I stopped and spoke to the contractor. He called Heartland to have them come out and take down the cones to open the lanes. I will continue to monitor.

Corrective Action Required

3	Misc	Site visit. Work was completed. TTC is no longer needed.

Comments: