MEMO via fax

Date: May 3, 2021

To: **Landrock**

From: Dan Webster, AIA dan@websterarchitects.com

Copy:

Attachments:

Subject: 3222 SW Pergola Park Drive – Permit #Prres20204069

1. The LVL valley rafters in the loft need to be braced to the wall below. LVl's need to be added in the floor below. See attached drawings.

2. For the stacked plates in the Master Suite, install straps every 4' on the interior side of the wall.

3. Since the hole in the LVL is outside of the structural span of the portal frame area and since it is reinforced with the sheathing, nothing additional is needed.

STATE OF MISSOURI
DANIEL J.
WEBSTER
NUMBER
A-5400
REGISTERED ARCHITECT

5-3-21

11060 South Green Road • Olathe, KS 66061-8429 • 913-390-4663

www.websterarchitects.com