CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #:   PRCOM20191614
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Wednesday, September 29, 2021

Informational:
1   THIRD FLOOR   —AREAS APPROVED—

                                 BUIDING C
                                 COMPLETE

                                 BUILDING B
                                 COMPLETE

                                 BUILDING A*
                                 -COMPLETE

Informational:
2   SECOND FLOOR   —AREAS APPROVED—

                                 BUILDING C
                                 COMPLETE

                                 BUILDING B
                                 COMPLETE

                                 BUILDING A
                                 CORRIDOR CEILINGS TO SHAFT WALL

COMPLETE EXCEPT 2044

Informational:

3   FIRST FLOOR   —AREAS APPROVED—

BUILDING C
CORRIDOR CEILINGS TO SHAFT WALL
ROOMS:1015,1017,1020-1030
STAIRWELL WALLS AND CEILING

BUILDING B
CORRRIDOR CEILNGS TO SHAFT WALL
ROOMS: 1002-1015
STAIRWELL WALLS AND CEILING

BUIDING A
CORRIDOR CEILNG TO SHAFT WALL
EXTERIOR WALL 1032 OK TO INSULATE
STAIRWELL WALLS AND CEILING
ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059, 1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058
ROOM 1041 OK FOR SOFFIT FRAMING
STAIRWELL WALLS AND CEILING
SOFFIT FRAMING 1049,1052, CORRIDOR1060,1036

MCAL BUILDING
--- PRE ROCK:
 MECHANICAL ROOM 165 NORTH WALL
 ROOM 156
 Kitchen 164 OK-CEILING OK FOR ROCK NOT AT HOODS
CORRIDOR 167 TO 10' FROM SHAFT WALL
CORRIDOR 169,172,176,177a,177 to rm 135, 173, 34,39,42
MC EXTERIOR WALLS OK FOR FOAM
MC SHARED SPACES OK FOR RC 149-160, 162,162A,163 to truss repair, 174, 174A,175,179A

MC UNITS 1-18, 21,24,25,28-33, 36,37,45
SHARED SPACES: 149,150,152,153,154,157,159,161,162, 162A,174,174A,175
AL UNITS: 102-147

Corrective Action Required:

4   Miscellaneous   2044-INCOMPLETE
         Correction   2045-INCOMPLETE
                            024-REPAIR TRUSS
                            COMPLETE DRY SYSTEM IN ATTIC

Comments: