CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

STOP WORK ORDER

ANY UNAUTHORIZED PERSON REMOVING THIS NOTICE WILL BE PROSECUTED

Permit #: PRRES20242945

Address: 3718 SW KNOXVILLE CT, LEES SUMMIT, MO 640823716 SW KNOXVILLE CT,

LEES SUMMIT, MO 64082

Any person who shall continue work after having been served with a stop work order, except such work as that person is directed to perform to remove a violation or unsafe condition, shall be subject to penalties as prescribed by law.

Inspection: Outcome: Date:

Erosion Control Jamie Simerly Failed - Stop Work Monday, July 28, 2025

Inspection Residential

Informational

Miscellaneous Correction Erosion control measures are in place and must be properly maintained until CofO

Corrective Action Required

2 DCM3 ESC REQUIRED 2 07/21/25 Jamie S, Additional erosion control needs to be

DAY established in the yard. Silt is washing over driveway on to the street and sidewalk causing a safety hazard for residents.

Erosion control needs to be maintained until lot has 70 percent

vegetation.

EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN

COMPLIANCE WITHIN TWO BUSINESS DAYS.

07/24/25 Jamie S, Silt has been cleaned up. Landscaping measures have been into place for preventing silt. Putting on partial correction because vegetation is still not at 70 percent

and silt fence is not currently installed.

07/25/25 Jamie S, Erosion control needs to be reestablished. Landscaping measures have started to erode away on to the driveway and into the street. Driveway, sidewalk, and

220 SE Green Street | Lee's Summit, MO 64063 | 816.969.1200

CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

construction debris need to be cleaned off the lot. 07/28/25 Jamie S, Erosion control needs to be reestablished. Landscaping measures have started to erode away on to the driveway and into the street. Driveway, sidewalk, and construction debris need to be cleaned off the lot.

Comments: