CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20235208

Address: 2911 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Khanh Nguyen	Failed	Monday, July 28, 2025
Corrective Action Required: LOWER LEVEL Corrective Action Required: FIRST FLOOR Corrective Action Required: SECOND FLOOR Corrective Action Required: THIRD FLOOR Corrective Action Required: FOURTH FLOOR	Pre-rock for corridor of Pre-rock for corridor of **Check all -Framing of balcony of -Complete corridor electrons and the second	eiling-OK eiling not per plan ectrical	at over-bored stud; protect
	/II I = '		

	-Missing studs at bath and laundry walls
	406:
	405:
	408:
	407:
	410:
	409:
	412:
	413:
	411:
Corrective Action Required:	
6 STAIR TOWER 1	
Corrective Action Required:	
7 STAIR TOWER 2	
Corrective Action Required:	
8 STAIR TOWER 3	
Corrective Action Required:	
9 ELEVATOR 1	
Corrective Action Required:	Interior and outputon about od at a second
10 Misc	Interior and exterior sheathed shear walls:
	-Lower floor, 1st, 2nd fl

Comments: