## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## OnlinePortal at DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRRES20252080

Address: 1304 SE WINDBREAK DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, August 15, 2025

Residential

Corrective Action Required:

1 Miscellaneous

Correction -strap top plate where lapped less than 24" E garage wall

-fire block kitchen/stairwell wall in furr down

-maximum 2 NM through each top plate penetration. See pwdr room. Check

throughout

-fire block pdwr room wall to garage wall furr down

-rear walls not framed to cspf specifications

-uncover covered front porch

-protect dryer vent at top plate. Protection shall extend 2" bellow top plate

-solid block sheathing breaks where sheathing does not extend to top plate

throughout 2nd floor(nail according at exterior and to top plate)

-proving blocking under kitchen island

-plans call for (3) 2x6 at rear basement under beam each side

-use approved connector for ufer ground connections

-install bonding screw at main disconnect

-no pressure at gas line

## **Comments:**