

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20250074
Address: 632 SE WOOD LN, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Tuesday, August 19, 2025

Corrective Action Required:
3 Misc

- Fire block wall space to ceiling space at return air furr down
- missing hold down at T06 truss above primary bedroom
- missing hold downs on T05 truss above primary bath
- trusses above garage do not match plans and do not have proper hold downs in multiple areas
- smoke/CO required in the immediate facility of bedrooms. See bed 2
- bonding screw for all metallic boxes to be compliant with 250.126 of NEC

Comments: