

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20236023

Address: 3201 NE WILSHIRE DR, LEES SUMMIT, MO 64064551 NE MEADOWVIEW DR, LEES SUMMIT, MO
640643200 NE WILSHIRE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection	Nick Scott	Partial	Tuesday, August 19, 2025

Corrective Action Required:

1	Misc	Retirement home 10-14-24 NS Gutter buddies need to be installed around construction site 10-31-24 NS Site Visited and no work has been done since last inspection 11-6-24 NS Site Visited and still no erosion control issues 11-13-24 NS Site Visited and still no erosion control issues 12-13-24 NS Site Visited and still no erosion control issues 12-31-24 NS Site Visited and still no erosion control issues 1-10-25 NS Site Visited and still no erosion control issues 1-16-25 NS Site Visited and still no erosion control issues 1-24-25 NS Site Visited and still no erosion control issues 1-31-25 NS Site Visited and still no erosion control issues 2-3-25 NS Site Visited and still no erosion control issues 2-10-25 NS Site Visited and still no erosion control issues 2-17-25 NS Site Visited and still no erosion control issues 2-24-25 NS Site Visited and still no erosion control issues 2-28-25 NS Site visited and it appears that no erosion control issues 3-6-25 NS Site visited and it appears that no erosion control issues 3-19-25 NS Site visited and saw fence down and the company went out while I was there. 4-3-25 NS Site visited and drove around jobsite and it appears that site does
---	------	---

not have a problem.

4-16-25 NS Site visited and it appears concrete spilled and the crew is cleaning it up.

4-24-25 NS Site visited and it appears that jobsite has no problems

7-22-25 NS Site visited and it appears that jobsite has no problems

8-5-25 NS Site visited, and it appears that erosion control is correct. I would still like erosion control fence around the big dirt pile on jobsite.

8-19-25 NS Site visited and it appears that erosion control is working properly. but fence still has not be installed at this moment around the dirt pile.

Comments: