

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20252492, Public Works Right of Way Permit Address: 2690 NE HAGAN RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Eric Wiggins Partial Wednesday, September 03,

2025

Corrective Action Required

1 Misc Site visit. Crews are on site. Work is just starting. I will continue

to monitor. The road is closed and the TTC is set up correctly.

Corrective Action Required

2 Misc The duck bank has been dugout, and they are starting to cast it

in place. I will continue to monitor.

Corrective Action Required

3 Misc Site visit. The duct bank has been constructed. They will begin

patching the road back with flow fill and then 10 inches of concrete in the next few days. I will continue to monitor the

site.

Corrective Action Required

4 Misc Site visit. Bob and I meet with Black and McDonald this morning

to go over where the duct banks will be, and on where the ROW is through out the project. I will continue to monitor.

Corrective Action Required

5 Misc Site visit. Work is continuing along Hagan Rd. They have dug 2

more locations for the duct banks in the ROW. The site is being kept clean and Hagan road remains closed at this time. I will

continue to monitor.

Corrective Action Required

6 Misc Pits are fenced. ESC needs to be installed. I had a conversation

with the superintendent about ESC.

Corrective Action Required

7 Misc The crew onsite is installing ESC today including inlet

protection, waddles, and straw matting.

Corrective Action Required

8 Misc

Crews have placed erosion control around the storm inlets.

Corrective Action Required

9 Misc Site visit. Crews are on site working. They are moving down

Strother Rd. towards Lee's Summit road. The site is being keep clean. I will continue to monitor.

Corrective Action Required 10 Misc

Site visit. Workers were present. Currently they are working along strother rd. They do not have any open pits right now, it appears they are working on restoring where they have already been. I will continue to monitor.

Comments: