

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20220363, Public Infrastructure

Address: 3905 SW FLINTROCK DR, LEES SUMMIT, MO 640823909 SW FLINTROCK DR, LEES SUMMIT, MO
640823913 SW FLINTROCK DR, LEES SUMMIT, MO 640823917 SW FLINTROCK DR, LEES SUMMIT, MO
640823921 SW FLINTROCK DR, LEES SUMMIT, MO 640823925 SW FLINTROCK DR, LEES SUMMIT, MO
640823929 SW FLINTROCK DR, LEES SUMMIT, MO 640823933 SW FLINTROCK DR, LEES SUMMIT, MO
640824012 SW MONDAVI LN, LEES SUMMIT, MO 640824008 SW MONDAVI LN, LEES SUMMIT, MO
640824004 SW MONDAVI LN, LEES SUMMIT, MO 640824000 SW MONDAVI LN, LEES SUMMIT, MO
640824001 SW MONDAVI LN, LEES SUMMIT, MO 640824005 SW MONDAVI LN, LEES SUMMIT, MO
640823949 SW FLINTROCK DR, LEES SUMMIT, MO 640823953 SW FLINTROCK DR, LEES SUMMIT, MO
640823952 SW FLINTROCK DR, LEES SUMMIT, MO 640823948 SW FLINTROCK DR, LEES SUMMIT, MO
640823944 SW FLINTROCK DR, LEES SUMMIT, MO 640823940 SW FLINTROCK DR, LEES SUMMIT, MO
640823936 SW FLINTROCK DR, LEES SUMMIT, MO 640823932 SW FLINTROCK DR, LEES SUMMIT, MO
640823928 SW FLINTROCK DR, LEES SUMMIT, MO 640823924 SW FLINTROCK DR, LEES SUMMIT, MO
640823920 SW FLINTROCK DR, LEES SUMMIT, MO 640823916 SW FLINTROCK DR, LEES SUMMIT, MO
640823912 SW FLINTROCK DR, LEES SUMMIT, MO 640823908 SW FLINTROCK DR, LEES SUMMIT, MO
640823904 SW FLINTROCK DR, LEES SUMMIT, MO 640824009 SW MONDAVI LN, LEES SUMMIT, MO
640823900 SW FLINTROCK DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Matt Munger	Failed	Monday, September 08, 2025

Corrective Action Required

1	Misc	Bond Inspection - the road is starting to fail by lot 192 or 3916 SW Flintrock next to the storm inlet. The area has been marked in pink.
---	------	---

Comments: