CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20250069

Address: 640 SE WOOD LN, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, September 12,

Residential 2025

Corrective Action Required:

2 Misc

Truss plans must be city approved.

- -fireblock garage walls into furr down
- -bonding screw missing at metallic boxs
- -end condition 4 call out in blue prints does not have detail
- -stair truss repair not nailed to stamped fix
- -missing CS-Pf nailing at rear
- -seal penetrations and gaps in draft stopping
- -protect all wiring within 6' of attic access
- -protect dryer vent 2" below top plate penetration
- -protection for dwv shall extend 2" below top plate
- -missing hold downs for trusses above dead space at laundry
- -T02 truss above primary bedroom does not match plans
- -missing hold downs on T03 truss above primary bedroom
- -land all ground and neutrals in panel
- -missing ufer ground connection
- -bond meter can

Comments: