

Environmental
Geotechnical Engineering
Geophysical Technology
Materials Testing
Field Inspections & Code Compliance

September 23, 2025

Mr. Brian Maenner Vice President of Development Intrinsic Development 3622 Endeavor Avenue Columbia. Missouri 65201

RE: Special Inspection Report No. 4

Discovery Park Pet Spa

1921 NE Trails Edge Boulevard

Lee' Summit, Missouri

Report Period: July 27, 2025 to September 20, 2025

Permit No.: PRCOM20243938 UES Project No.: A23129.00089.007 Legacy Project No: J044702.08

Dear Mr. Maenner:

This letter with attachments will constitute our Special Inspection transmittal for the above referenced project. Representatives of UES have provided field observation and testing services for drilled and epoxy-grouted anchors and wood framing during the report period. Our services have been provided on a part-time basis as scheduled by representatives of Goebel Mitts Construction. The compliance of materials or work not observed by our personnel is not addressed, or implied, by this or any previous report.

#### **Summary of Activities**

### **Drilled and Epoxy-Grouted Anchors**

Installation of the drilled and epoxy-grouted anchors for the shear walls into the existing foundations was observed on August 4. The drilled holes were observed for the required location, depth, diameter, and cleaning procedures. Installation of the all-thread dowels was observed with respect to the project documents for the specified anchor bolt diameter, grade, embedment, projection, and type of epoxy used.

#### Wood Framing

The wood framing and shear walls for the building were observed on July 31 and August 6. The wood framing was observed for anchoring type and spacing, opening header type and count, stud and shear wall framing type and spacing, member size, location, and connection geometry. The OSB sheathing for the shear walls was observed for the type, thickness, and joint location indicated in the project documents. The nail patterns to the wall framing were compared with the project documents for the required nail size and spacing. The shear wall hold-down brackets, truss hangers, tie down brackets, and coil straps were observed for the required type, configuration, and installation type.

### **Status of Compliance**

The specific items discussed above in this report appeared to be in general compliance with the contract documents.

## Closure

The results of our field observations and testing were reported to authorized personnel during our site visits. If you have any questions regarding this report, or if we may be of further service, please contact us.

Respectfully submitted,



Steve Damron

**CMT** Department Manager

cc: Mr. Joe Frogge – City of Lee's Summit

Mr. Aaron Addis – Intrinsic Development

Mr. John Grahovac – Intrinsic Development

Mr. Forrest Walsh – Intrinsic Development

Mr. AJ Dolph - Rosemann & Associates, PC

Ms. Cindy Senecal – McClure Vision

Mr. Dustin Heitman – Goebel Mitts Construction

UES S.I. File

# Discovery Park Pet Spa Variance/Discrepancy List

NOTE: Items resolved during the report period are shaded

Description

Variance Date Date
Number Opened Closed

\_