

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20253127
Address: 2124 SW WHEATFIELD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection Residential	Tyler Schreck	Failed	Friday, October 17, 2025

Corrective Action Required:

1	Misc	10/17/25 Tyler S. Concrete CANNOT run into storm drain. Concrete was washed out close to curb and then drained under the straw waddle into the curb and down into the storm drain. Erosion control must be installed properly and functioning properly. Concrete wash out can be build too. Need to get this corrected ASAP.
---	------	--

Comments: