

Professional Service Industries, Inc. 2828 South 44th Street Kansas City, KS 66106

CC:

Phone: (913) 310-1600 Fax: (913) 310-1601

Steel Observation Report

HCA MANAGEMENT SERVICES, LP

P.O. BOX 550 BLDG 3-2

NASHVILLE TN 37202-0550

Project: LEE'S SUMMIT MEDICAL CENTER

Report No.: OS:03534146-24-01

Issue No.:

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a noncompliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement. Tests and inspections are considered to be simple acceptance criteria unless noted otherwise.

North Sahafaia

2100 SE BI	LUE PKWY	Approved Signatory: Mahdi Sahafnia Date of Issue: 10/23/2025	Staff Engineer				
General Details Date: 10/22/2025 General Nubohlz Contractor: Clear Weather: Permit:	Location(s)/Item Roof framing and welding except mo	welding, nelson studs and decking at Lin	Technician: e H-K.4/11-19 all Subcontractor Product Name Product Manu	: :			
1. Type(s) of Observation P Special Inspection New Inspection	Performed & General Checklist AWSQC1/ASNT VT Re-Inspection	At Completion Continuous	In Progress Periodic	Post-Completion*			
Structural Welding Shop Field Weld Process IC	Structural Bolting Pretension Shear Brg Bolts Specified IC	Steel Erection Shop Field Joint Details IC	Post-Installed Anchors Chemical Mechanical ICBO Report No:	Open Web Steel Joist Inspection Shop Field Joist Girder Seat Connections			
Electrode IC Weld Profiles(s) IC	Turn-of-Nut NA Cal. Wrench NA	Erection Dwgs IC Inspection Rpts IC	Anchor Type Adhesive Type	Joist Seat Connections Horiz. Bridging Connections			
Welder Cert(s) IC Weld Prcdr(s) IC Mill Cert(s) IC	Tension Control IC Snug Tight NA Hardened Washers IC	Mark No.s IC Anchor Bolts IC Columns IC	Hole Diameter Embed Depth Manuf. Instruct's	X-Bridging Connections Wind Brace Connections Bottom Girder Braces			
Prep & Fit-Up IC Preheat Temp IC □UT □MT □RT □PT	Tighten Sequence IC Faying Surfaces IC Skidmore Tests	Beams IC Metal Deck/Studs IC X-Bracing IC	Clean & Dry Adequate Adhes. Torqued/Tight	RTU Joist Reinforcement			
Box Definitions: X=Attac	ched; IC=In Compliance; NA=Not A laterials, Workmanship & Proced	Applicable; NC=Nonconformance		s Below or Contact Bldg Dept.			
2.1 Referenced Details/Drawings: S302, S124B, S123B							
2.2 Non-Conformance #: 2.3 Parties Notified: General Contractor Subcontractor Architect Subcontractor Other: 2.4 Name / Title of notified party: NUbohlz 2.5 To the best of my knowledge, the work inspected above was in accordance with the building department approved design drawings, specifications and applicable workmanship provisions of the International Building Code:							
Except As Noted Not Applicable Unapproved Drawings/Plans/Materials NCR Issued Non-Compliance Required Requires Engineers Acceptance(RFI) Inspector: Eric Behrens ID Number: Standby Time:							
Remarks:							

Remarks:							
Jobsite / Shop Representative: In Compliance or Not in Compliance							
DISCREPANCIES							
Discrepancy ID	Item	Location	Description/Corrective Action	Status			
				_			
				_			
	ļ			_			