

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20250692
Address: 2614 SW FIREFLY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control Inspection Residential	Tyler Schreck	Failed	Monday, November 24, 2025

Corrective Action Required:

1	Misc	10/31/25 Tyler S. Field inlet in the back corner of the property does not have erosion control around it. The silt fence that was there is down and needs put back up. 11/24/25 Tyler S. Curb inlet on the south side of the driveway has too much trash mud and debis in it and is keeping the waddle from properly doing its job. Please clean out ASAP. Also, 2x4s and form scraps have spilt over silt fence and need to be pushed back and fence needs put back up.
---	------	---

Comments: