

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**OnlinePortal at DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20252864  
Address: 1505 SE BAILEY FARMS PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mitchell Schwarz	Failed	Tuesday, November 25, 2025

Corrective Action Required:

1	Misc	-fireblock hvac chase to furr down and ceiling space in garage -missing studs at LIB wall Bed 5, tighten LIB, strap should not be lose(lib requires 16" OC stud spacing) - protect all wiring within 6' of attic access - fire block pex into pantry furr down - add strap at top plate penetration for plumbing vent at great room/bath 3 - add a 2nd strap at top plate seam in bed 2
---	------	--

**Comments:**