

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20252864
Address: 1505 SE BAILEY FARMS PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mitchell Schwarz	Not Ready	Monday, December 01, 2025

Corrective Action Required:

1	Misc	-missing studs at LIB wall Bed 5, tighten LIB, strap should not be lose(lib requires 16" OC stud spacing) - fire block pex into pantry furr down - add a 2nd strap at top plate seam in bed 2
---	------	---

Comments: