



HEARTLAND TRUSS
 500 MID AMERICA DRIVE
 PLATTSBURG, MO 64477

 P: 816-930-3177

 BY: JOHN FITZGERALD



84 LUMBER / REUNION AT BLACKWELL
 BUILDING TYPE A (2 STEPS) 12 INCH
 S.E. SHENANDOAH DRIVE
 LEE'S SUMMIT, MO.

 JOB: 251348 ROOF LAYOUT

 DATE: 9/29/2025

Concrete was poured wrong and trusses do not extend over wall. Our solution to this is to run a header on top of the wall and hanger all trusses into that.

RELEASED FOR CONSTRUCTION
 As Noted on Plans Review

 Development Services Department
 Lee's Summit, Missouri
 12/05/2025

STAND STRUCTURAL ENGINEERING
 8234 Robinson St
 Overland Park, KS 66204
 (913) 214-2169

Reviewed Revise and Resubmit
 Reviewed as Noted Rejected
 Not required by the Contract Documents
 For Record Only

Review is only for general conformance with the design concept and the intent of the Contract Documents. Contractor is solely responsible for verifying dimensions, for establishing fabrication processes, means, techniques, sequences and procedures of construction and for coordination of work of all trades. Review action taken and noted to information shown does not authorize deviations from the intent of the contract documents, unless so stated in a separate letter or Change Order. The Structural Engineer and/or Architect-of-Record retained by the Contractor or his Supplier, for the Design / Build portion of the project represented by this submittal, is solely responsible for the correctness, appropriateness and adequacy of the Design / Build system.

By: JFunk
 Date: 11/13/2025