



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	OUR LADY OF THE PRESENTATION		
ADDRESS	130 NW MURRAY RD, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	A L HUBER INC:	TELEPHONE	(913) 341-4880
ADDRESS	10770 EL MONTE OVERLAND PARK, KS 66211 Primary: (913) 341-4880 Cell: <NO CELL PHONE> Kelly Lynch @ 913-208-8959		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-3	Map#: 195E	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # prcom20115556

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection 4/19/12

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Alarm Test	Joe Dir	Passed	Thursday, April 19, 2012
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Thursday, April 19, 2012
Corrective Action Required:			
1 (1) removed door labeling from old sprinkler room door (2) label access doors to new sprinkler riser (3) label all sprinkler riser valves (4) label the FDC with wording indicating coverage of sprinkler sys. (tower/south wing) (5) mount knox box by the fdc approx 6' off ground (6) keys needed for knox box: main FACP pull stations exterior access door sprinkler room doors padlock key to the corridor cages			

(70 attempt to have duct detectors programed as supervisory with hvac shutdown
OK for TCO once cleared through codes administration

Sprinkler - Hydrostatic Test Joe Dir Passed Tuesday, March 20, 2012

DATE OF REPORT

April 19, 2012

INSPECTOR

Joe Dir

PREVENTION FOLLOW-UP
REQUIRED?



Yes



No

RESPONSIBLE SIGNATURE