

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20214053, Public Infrastructure

 Address: 2829 SW HEARTLAND RD, LEES SUMMIT, MO 640822825 SW HEARTLAND RD, LEES SUMMIT, MO
 640822821 SW HEARTLAND RD, LEES SUMMIT, MO 640822817 SW HEARTLAND RD, LEES SUMMIT, MO
 640822813 SW HEARTLAND RD, LEES SUMMIT, MO 640822809 SW HEARTLAND RD, LEES SUMMIT, MO
 640822805 SW HEARTLAND RD, LEES SUMMIT, MO 640822759 SW HEARTLAND RD, LEES SUMMIT, MO
 640822755 SW HEARTLAND RD, LEES SUMMIT, MO 640822751 SW HEARTLAND RD, LEES SUMMIT, MO
 640822747 SW HEARTLAND RD, LEES SUMMIT, MO 640822743 SW HEARTLAND RD, LEES SUMMIT, MO
 640822739 SW HEARTLAND RD, LEES SUMMIT, MO 640822735 SW HEARTLAND RD, LEES SUMMIT, MO
 640822731 SW HEARTLAND RD, LEES SUMMIT, MO 640822734 SW HEARTLAND RD, LEES SUMMIT, MO
 640822742 SW HEARTLAND RD, LEES SUMMIT, MO 640822750 SW HEARTLAND RD, LEES SUMMIT, MO
 640822222 SW CROWN DR, LEES SUMMIT, MO 640822226 SW CROWN DR, LEES SUMMIT, MO
 640822230 SW CROWN DR, LEES SUMMIT, MO 640822234 SW CROWN DR, LEES SUMMIT, MO
 640822233 SW CROWN DR, LEES SUMMIT, MO 640822229 SW CROWN DR, LEES SUMMIT, MO
 640822225 SW CROWN DR, LEES SUMMIT, MO 640822221 SW CROWN DR, LEES SUMMIT, MO
 640822218 SW HEARTLAND CT, LEES SUMMIT, MO 640822222 SW HEARTLAND CT, LEES SUMMIT, MO
 640822226 SW HEARTLAND CT, LEES SUMMIT, MO 640822230 SW HEARTLAND CT, LEES SUMMIT, MO
 640822234 SW HEARTLAND CT, LEES SUMMIT, MO 640822233 SW HEARTLAND CT, LEES SUMMIT, MO
 640822229 SW HEARTLAND CT, LEES SUMMIT, MO 640822225 SW HEARTLAND CT, LEES SUMMIT, MO
 640822221 SW HEARTLAND CT, LEES SUMMIT, MO 640822217 SW HEARTLAND CT, LEES SUMMIT, MO
 640822213 SW HEARTLAND CT, LEES SUMMIT, MO 640822835 SW HEARTLAND RD, LEES SUMMIT, MO
 640822240 SW HEARTLAND CT, LEES SUMMIT, MO 640822737 SW HEARTLAND RD, LEES SUMMIT, MO
 640822222 SW CROWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
PW Bond Inspection	Matt Munger	Failed	Monday, December 22, 2025

Corrective Action Required

1	Misc	Bond Inspection - there are several sanitary sewer manholes where the pavement has settled around them. These settlement issues will need to be addressed and concrete diamonds installed. Below are the addresses closest to the manholes in pavement. Pics are attached.
		2731 SW Heartland in the cul-de-sac 2234 SW Crown 2222 SW Heartland Ct.

2829 SW Heartland Ct.

Comments: