



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	HAWTHORN BANK - LONGVIEW		
ADDRESS	300 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	PFEIFER KING BUILDING CORP.:	TELEPHONE	(816) 524-4986
ADDRESS	1550 SW MARKET ST. LEE'S SUMMIT, MO 64081 Primary: (816) 524-4986 Cell: (816) 215-1200 Rick @ 215-5041		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: B	Map#: 194E	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # prcom20115721/ 5800

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection 5/2/12

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Passed	Thursday, May 03, 2012
Corrective Action Required: 1 occupancy inspection; appeared ok at the time of the inspection, ok to occupy once cleared through codes administration. two sprinkler head eschutions needed in office areas			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
May 03, 2012	Joe Dir	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	