



# LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



## NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

### ☐ CHANGES

BUSINESS NAME	HY-VEE GAS #2		
ADDRESS	1201 SW 3RD ST, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	HY-VEE WEITZ CONSTRUCTION:	TELEPHONE	(816) 645-2300
ADDRESS	5605 NE 22ND ST DES MOINES, IA 50313 Primary: (816) 645-2300 Cell: <NO CELL PHONE> Steve @ 515-229-3589		

## EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

## LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#: 195E	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20112705

## LOSS REDUCTION NARRATIVE

### ☐ NO VIOLATIONS NOTED

### ☒ ALL VIOLATIONS RESOLVED

Last Inspection      1st Inspection 8/24/12      2nd Inspection      3rd Inspection      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Passed	Friday, August 24, 2012
Corrective Action Required: ALL PENDING ISSUES HAVE BEEN RESOLVED			
1 label emergency fuel shut-offs at check-out counter and the exterior of bldg. mount fire extinguishers on exterior of bldg, one at the 911 phone/ fuel shut-off another on the middle -east fuel dispenser pole -install all necessary labeling on all fuel dispensers -activate the exterior 911 phone - post the buildings numeric address "1201" on the exterior of the building, readable from 3rd street. -all fuel pump safety dic-connects under pumps need to be connected -need a second phone-line / dialer for the alarm system			
Storage Tanks Inspection	Joe Dir	Partial	Wednesday, May 16, 2012

**Storage Tanks Inspection** Joe Dir Passed Thursday, May 31, 2012

**Occupancy Inspection - Fire** Joe Dir Not Ready Thursday, August 09, 2012

Corrective Action Required:

- 1 label emergency fuel shut-offs at check-out counter and the exterior of bldg.  
mount fire extinguishers on exterior of bldg, one at the 911 phone/ fuel shut-off another on the middle -east fuel dispenser pole  
-install all necessary labeling on all fuel dispensers  
-activate the exterior 911 phone  
- post the buildings numeric address "1201" on the exterior of the building, readable from 3rd street.  
-all fuel pump safety dic-connects under pumps need to be connected  
-need a second phone-line / dialer for the alarm system

**Alarm Test** Joe Dir Passed Thursday, August 09, 2012

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
August 24, 2012	Joe Dir	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	