

## CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

## **Inspection Summary**

Permit #: PRCOM20121405, Building Permit - Commercial Address: 178 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy John Borns Failed Friday, November 16, 2012

Inspection - Codes Commercial

Corrective Action Required

1 MISC RESOLVE ISSUES WITH FIRE DEPARTMENT AND WATER

**DEPARTMENT** 

Corrective Action Required

2 MISC INSTALLATION OF LIGHTED SIGN SUBJECT TO APPROVAL

WHEN INSTALLED. PER NEC 600-3: IF INTERNALLY LIGHTED

MUST BE UL SHOP-LABELED PER 600.3. INSTALL NO

NON-LISTED SIGN.

Corrective Action Required

3 MISC LS CODE OF ORDINANCES 17-309: DISPLAY OF "NO SMOKING"

SIGN(S) REQUIRED AT PUBLIC ENTRY(IES). SHALL LS CODE OF

ORDINANCES 17-309: DISPLAY OF "NO SMOKING" SIGN(S)

REQUIRED AT PUBLIC ENTRY(IES). SHALL BE CONSPICOUS AT

EACH PUBLIC POINT OF ENTRY.

BE CONSPICOUS AT EACH PUBLIC POINT OF ENTRY.

Corrective Action Required

4 MISC

COMPLETE ALL CONSTRUCTION ACTIVITY

Corrective Action Required 5 MISC

REVISIONS OF ELECTRICAL SERVICE CONFIGURATION

PRESENTLY SUBMITTED FOR APPROVAL MUST BE APPROVED

BEFORE SERVICE CAN BE INSPECTED.

Corrective Action Required

6 MISC GLAZING AT HAZARDOUS LOCATIONS SUBJECT TO APPROVAL

WHEN INSTALLED.

Corrective Action Required MISC

COMPLETE ELECTRICAL PANEL SCHEDULES INCLUDING **DESIGNATING ALL SPARES** 

Corrective Action Required **MISC** 

NEC 370-20; IRC E3806.5-6 SET-BACK OF ELECTRICAL RECEPTACLE / SWITCH BOXES: MUST BE FLUSH WITH COMBUSTIBLE WALL SURFACE; 1/4" MAXIMUM SET-BACK @

NON-COMBUSTIBLE SURFACES

Corrective Action Required 9 MISC

BUILDING FACADE, SOFFIT BELOW, AND ALL ASSOCIATED REMAINING WORK SUBJECT TO APPROVAL WHEN READY FOR INSPECTION

Corrective Action Required **MISC** 10

EXPOSED GAS PIPING NOT PAINTED BELOW UPPER ROOF

Corrective Action Required MISC

IDENTIFY RTU's: DESIGNATE ADDRESS NUMBER AND RTU NUMBER

Corrective Action Required MISC

ELECTRICAL RECEPTACLES AT RTU'S NOT HOT FOR TEST

Corrective Action Required MISC 13

REMOVE ALL DEBRIS AND UNUSED MATERIAL FROM ROOFTOP

Corrective Action Required **MISC** 14

ADDRESS LABELING OF GAS SERVICE ENTRY PIPE: AFFIX PERMANENT TAG/LABEL TO LOAD SIDE PIPE. FELT TIP

MARKER NOT APPROVABLE.

## **Comments:**