



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	BIG LOTS		
ADDRESS	901 SE LANGSFORD RD, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	ALLIED RETAIL CONCEPTS LLC:	TELEPHONE	(913) 492-8008
ADDRESS	6205 GODDARD ST SHAWNEE, KS 66203 Primary: (913) 492-8008 Cell: (816) 365-6153		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#: 195H	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # prcom20121736

LOSS REDUCTION NARRATIVE

☐ NO VIOLATIONS NOTED

☒ ALL VIOLATIONS RESOLVED

Last Inspection

1st Inspection

2nd Inspection 2/6/13

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Passed	Wednesday, February 06, 2013
Corrective Action Required: pending issues resolved			
1	<ul style="list-style-type: none">- restore the fire department connection for the sprinkler system back to working order.- need access keys for the store. (to lock in the knox box)- label the access door for the sprinkler room on the sales side of the door- lower sprinkler heads below the drop ceiling as needed located at the rear of the sales area- replace exterior water flow bell with a weatherproof horn/strobe- address exterior of the double doors to receiveing (southwest double doors) with numeric address of 901		
Alarm Test	Joe Dir	Passed	Monday, January 14, 2013
Sprinkler - Hydrostatic Test		Not Required	Thursday, December 06, 2012

Sprinkler - Flow Test

Joe Dir

Failed

Monday, January 14, 2013

Occupancy Inspection - Fire

Joe Dir

Temporary C of O

Monday, January 14, 2013

Corrective Action Required:

- 1
- restore the fire department connection for the sprinkler system back to working order.
 - need access keys for the store. (to lock in the knox box)
 - label the access door for the sprinkler room on the sales side of the door
 - lower sprinkler heads below the drop ceiling as needed located at the rear of the sales area
 - replace exterior water flow bell with a weatherproof horn/strobe
 - address exterior of the double doors to receiveing (southwest double doors) with numeric address of 901

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
February 06, 2013	Joe Dir	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	