



# LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



## NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

### ☐ CHANGES

BUSINESS NAME	Plato's Closet		
ADDRESS	1170 NE DOUGLAS ST, LEES SUMMIT, MO 64086		
OWNER/OPERATOR NAME	BUDDEMEYER CONSTRUCTION:	TELEPHONE	<NO PRIMARY PHONE>
ADDRESS	4223 FURLONG DR LEE'S SUMMIT, MO 64082 Primary: <NO PRIMARY PHONE> Cell: (816) 419-3526 Ron Cerra @ 816-215-0775		

## EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

## LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#: 195B	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20110161

## LOSS REDUCTION NARRATIVE

### ☐ NO CORRECTIONS NOTED

### ☐ ALL CORRECTIONS COMPLETED

Last Inspection      1st Inspection 3/25/11      2nd Inspection      3rd Inspection      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Friday, March 25, 2011
Corrective Action Required:			
1	post the designated address on the front and rear doors of 1170, 4" min. in a contrasting color		
Corrective Action Required:			
2	mount 2A-10BC fire extinguisher close to an exit with the top of the extinguisher no higher than 60" off floor.		
Corrective Action Required:			
3	replace the painted sprinkler head located above the middle front entry door.		
Corrective Action Required:			
4	cover the open j-box located above the storage room door at the rear of the store.		
Alarm Test			
		Passed	Friday, March 25, 2011

<b>Sprinkler - Hydrostatic Test</b>		Not Required	Friday, March 25, 2011
<b>Sprinkler - Flow Test</b>		Not Required	Friday, March 25, 2011
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
March 25, 2011	Joe Dir	<input checked="" type="checkbox"/> <b>Yes</b> <input type="checkbox"/> <b>No</b>	