

☐ **CHANGES**

<b>BUSINESS NAME</b>	SEARS		
<b>ADDRESS</b>	232 NW OLDHAM PKWY, LEES SUMMIT, MO 64081		
<b>OWNER/OPERATOR NAME</b>	LUKE DRAILY CONSTRUCTION:	<b>TELEPHONE</b>	(816) 459-8531
<b>ADDRESS</b>	75 NW BUSINESS PARK LN RIVERSIDE, MO 64150 Primary: (816) 459-8531 Cell: (816) 215-4059		

**EMERGENCY CONTACT INFORMATION**

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

**LOSS REDUCTION TYPE**

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#: 195E	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20130503

**LOSS REDUCTION NARRATIVE**

☐ **NO VIOLATIONS NOTED**

☐ **ALL VIOLATIONS RESOLVED**

Last Inspection      1st Inspection      2nd Inspection      3rd Inspection      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
<b>Occupancy Inspection - Fire</b>	Joe Dir	Passed	Tuesday, July 23, 2013
Corrective Action Required: 1      add numeric address (232) to exterior of rear doors need access keys when locks get changed			
<b>Alarm Test</b>	Joe Dir	Passed	Monday, July 22, 2013
<b>Sprinkler - Hydrostatic Test</b>	Joe Dir	Not Required	Tuesday, July 23, 2013
<b>Sprinkler - Flow Test</b>	Joe Dir	Not Required	Tuesday, July 23, 2013

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
July 23, 2013	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	