



CITY OF LEE'S SUMMIT  
CODES ADMINISTRATION  
220 SE GREEN ST.  
P.O.BOX 1600

PHONE:  
816-969-1200

FAX:  
816-969-1201

## Inspection Summary

---

Permit #: PRCOM20122641, Building Permit - Commercial  
Address: 209 SE GREEN ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Commercial</b>	John Borns	Failed	Monday, August 19, 2013

### Corrective Action Required

1 MISC

RESOLVE ANY WATER UTILITIES ISSUES

### Corrective Action Required

2 MISC

RESOLVE ANY FIRE DEPARTMENT ISSUES

### Corrective Action Required

3 MISC

RESOLVE ANY PLANNING AND DEVELOPMENT ISSUES

### Corrective Action Required

4 MISC

ISSUES WITH ELECTRICAL RECEPTACLES:

A) SOME RECEPTACLES NOT SOLID TO BOX

B) SOME RECEPTACE DISPLAY OPEN GROUND

C) SOME RECEPTACLES DISPLAY HOT/NEUTRAL REVERSE

D) ENSURE ALL RECEPPTS HAVE COVER PLATES

\*\*\*\*\*CHECK ALL\*\*\*\*\*

### Corrective Action Required

5 MISC

NEC 408.4: LABELING OF ELECTRICAL CIRCUIT POSITIONS AT PANEL(S): EACH BREAKER POSITION MUST BE LABELED. MUST BE LEGIBLE, SPECIFIC. IF PANEL SCHEDULE IS USED NUMBER POSITIONS ON PANEL FRONT PER SCHEDULE. NO DITTO MARKS OR CONTINUATION SYMBOLS EXCEPT @ MULTIPLE POLE BREAKERS. LABEL UNUSED BREAKERS "SPARE"

### Corrective Action Required

6 MISC

COFFEE MAKER IF TO BE WATER-FED MUST HAVE APPROVED LOCAL BACKFLOW PROTECTION.

### Corrective Action Required

7 MISC

SAFETY INSPECTION AT ROOF SUBJECT TO APPROVAL.

**Comments: NO BUSINESS OPERATION PRIOR TO APPROVAL.**