

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRRES20130710, Building Permit - Residential

Address: 1629 NE SHADOW VALLEY DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection -Residential Khanh Nguyen

Failed

Monday, September 23, 2013

Corrective Action Required

1 MISC

- *HAVE PLAN ON SITE
- *COMPLETE GAS PIPING SYSTEM

FRAMING:

- -NAIL GARAGE PORTAL BRACE WALL SHEATHING TO SILL PLATE
- -ANCHOR SILL PLATE WITHIN 12" OF BREAK
- -FIREBLOCKING PER CODE THROUGHOUT-ALL FLOOR PENETRATIONS; ALL VERTICAL SPACES FROM HORIZONTAL SPACES; FIREPLACE WALL SPACE FROM FURDOWN; MASTER AREA WALLS FROM ROOF SPACE; BASEMENT WALL EVERY 10 FT (FILL THE GAP)
- -EXTERIOR GARAGE DOOR: FILL IN GAP AT HINGES; BLOCK JAMB STUD 3 STUD SPACES OUT
- -NAIL CORNER STUDS WITH 16D AT 12" INTERVAL OR EQUIVALENT NAILING
- -TOE-NAIL ALL JOISTS TO WALL TOP PLATES THROUGHOUT WITH MINIMUM 2-12D OR 3-8D
- -LAG LEDGEBOARD TO I BEAM WEB FRONT DINING
- -BLOCK UNDERNEATH POINT LOADS OF I BEAM ABOVE FRONT DINING
- -SHIM GAP AT RAFTER HANGERS ABOVE FRONT ENTRY DOOR
- -SUPPORT RIDGE EVERY 4 FT ABOVE PILE OF DUCTS

BETWEEN FRONT BED AMD MASTER BED

- -ATTIC ACCESS TO MAIN ROOF
- -RAFTERS ABOVE MASTER AREA-REDUCE SPAN TO 14'4"
- -AT MASTER AREA, NAIL SIDING TO STUDS AT STEP

FLASHINGS; SNOW-BLOCK STEP FLASHINGS

- -SUPPORT RIDGE ABOVE HYDROTUB
- -SUPPORT UNDERNEATH POINT LOAD OF MASTER BED WALL. CHECK PLAN, OR INSTALL DOUBLE JOISTS IF NOT ON PLAN

_

ELECTRICAL:

- -SHALL NOT USE WOOD SCREW TO BOND THE GROUNDING BAR TO EXTERIOR SUBPANEL ENCLOSURE. USE HIGH THREAD SCREWS
- -COMPLETE SOFFIT ELECTRICAL

MECHANICAL:

- -VENT ALL BATHFANS
- -PAN OFF RETURN AIR FROM ADJACENT SPACES. RA BELOW FRONT DINING (BOTH FLOOR AND WALL RA)

PLUMBING:

Comments:

-PROTECT 3" PLUMBING AT MUD CLOSET WALL

**DO NOT INSULATE

Inspection - Residential	Knanh Nguyen	Passed	Monday, September 23, 2013
Gas Service Inspection - Residential	Khanh Nguyen	Not Ready	Monday, September 23, 2013