

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20132180, Building Permit - Commercial

Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Friday, January 10, 2014

Inspection

Partial Correction

1 MISC OK TO COVER WHEN READY COMPONENTS OF RATED

MECHANICAL SHAFTS:

> SHAFT AT B'.2/18.5: "T" CROSS FRAMING & SHAFT LINER BOARD OK TO COMPLETE AND FIRE-SEAL; "T" STEM FRAMING W & N WALLS FRAMING & SHAFT LINER BOARD OK TO COMPLETE AND FIRE-SEAL; SHAFT AT B'.5/17.9: W & S WALLS FRAMING & SHAFT LINER BOARD OK TO COMPLETE AND FIRE-SEAL; SHAFT AT B'.2/17.1: FRAMING & SHAFT LINER BOARD OK TO COMPLETE AND FIRE-SEAL; [FRAMING AND LINER BOARD AT TYPE "F"

SHAFT IN 119 N WALL;

Partial Correction 2 MISC

GWB AT 1 HR FIRE-RATED WALLS: OK TO TAPE, MUD, & FIRE-SEAL WHEN READY 5/8" TYPE X GWB INSTALLATION @

FOLLOWING LOCATIONS: SPACE 136 S WALL 4' TOP-OUT; 143 S WALL; [137; 139; 141; 208; CORR CROSS-WALL @ DOOR A203; [COMMON WALL @ 056/057; ABOVE DOOR OPNG #203; 123

W,N,E WALLS; 124, 136 & 153 BOTH FACES;

Above Ceiling John Borns Partial Friday, January 10, 2014

Inspection

Partial Correction

1 MISC OK TO COVER WHEN READY GWB CEILING FRAMING +

ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: SHOWERS

@ 47-54; [SOFFITS AT CORRIDORS 203 & 207 @ (16), (16.4), (18.1), (18.4); LOBBYS 200 & 204;

NOT READY/NOT APPROVED: SOFFITS @ NURSE STATION; SOFFIT @ 062 E WALL. ENSURE TENSION STUDS ARE SCREWED BOTH FLANGES AT CONNECTIONS -- TOP AND BOTTOM.

In-wall Inspection John Borns Partial Friday, January 10, 2014

Partial Correction

1 MISC OK TO TOP-OUT WALLS WITH GWB TO ALLOW INSTALLATION

OF HVAC DUCT AND OTHER SYSTEMS AT FOLLOWING

LOCATIONS: CORRIDOR 5A203 FROM (13.1) TO (18.7); SPACE 140; 143; 162; CORR 5A207 FROM (19) TO (11); ON (17) FROM (B')

TO (C');

Partial Correction

2 MISC

OK TO COVER WHEN READY WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES: 5A115; 143; 070; 137; 139; 140; 141; 208; CORR 203 FROM (19) TO (17); PATIENT 047 THRU 059; 060 EXCEPT HEADWALL & SE PLUMBING WALLS IN BA; 061; CORR 201/202/203 COMPLETE FROM (19) TO (10.5) EXCEPT AT NURSE STATION DROPS/SOFFITS; CORRIDOR CROSSWALL @ FIRE DOOR 5A203; 016 THRU 046; RR133; RR134; 135 EXCEPT SE CORNER @ R.D. STACKS; 136; 147; 148; 149 N WALL; CORR 102 E & S WALLS FROM (8) TO (11); 060B; 203; CORR 207 W WALL (13.7) TO (19); 125 E,S,W WALLS; 153; 124; 206; 123; 121 EXCEPT SHORT WALL; 061A; 063; 062; CORR CROSS-WALL @ DOOR 102; CORR 102 W WALL FROM (8) TO (11); 037 THRU 046; 031 THRU

036; [ABOVE DOOR 207;

Comments: