

Inspection Summary

Permit #: PRCOM20130305, Building Permit - Commercial
Address: 10 NE TUDOR RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Failed	Wednesday, January 22, 2014

Corrective Action Required

1	MISC	USE & OCCUPANCY OF AREA "B": > RESOLVE FIRE DEPARTMENT ISSUES > NO WATER DEPARTMENT ISSUES PER BEN H. > RESOLVE ISSUES IN TOILET E119: SEE BELOW
---	------	---

Corrective Action Required

2	MISC	ACCESSIBLE TOILET E119: 1) 18" VERTICAL GRAB BAR LOCATION 2) MIRROR HEIGHT 3) PADDING AT UNDER-LAV PIPING 4) WALL SUFACES MUST BE NON-ABSORBENT 5) BASE MUST SEAL WALL-FLOOR JOINT
---	------	---

Comments: