

Inspection Summary

Permit #: PRCOM20130393, Building Permit - Commercial
Address: 194 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Failed	Thursday, January 23, 2014

Corrective Action Required

1	MISC	OBTAIN PLANNING & DEVELOPMENT DEPT APPROVAL. ANITICIPATE LATE MARCH COMPLETION.
---	------	---

Corrective Action Required

3	MISC	ENSURE ALL DIMENSIONS AT RESTROOMS ARE PER ADA/ANSI. SEE 18" GRAB BARS.
---	------	---

Corrective Action Required

5	MISC	ROOFTOP: > INSULATION ON REFRIGERATION TUBING NEEDS TO BE REPLACED. > CLEAR/CLEAN ENTIRE ROOF OF EXCESS MATERIAL & DEBRIS
---	------	---

Occupancy Inspection - Codes Commercial	John Borns	Failed	Thursday, January 23, 2014
--	------------	--------	----------------------------

Corrective Action Required

1	MISC	OBTAIN PLANNING & DEVELOPMENT DEPT APPROVAL. ANITICIPATE LATE MARCH COMPLETION.
---	------	---

Corrective Action Required

2	MISC	ENSURE ALL DIMENSIONS AT RESTROOMS ARE PER ADA/ANSI. SEE 18" GRAB BARS. TO BE READY FOR RE-INSPECTION 1/24/14.
---	------	--

Corrective Action Required

3	MISC	ROOFTOP: > INSULATION ON REFRIGERATION TUBING NEEDS TO BE REPLACED. > CLEAR/CLEAN ENTIRE ROOF OF EXCESS MATERIAL & DEBRIS TO BE READY FOR RE-INSPECTION 1/24/14.
---	------	---

Comments: