

CODES ADMINISTRATION

Inspection Summary

Permit #: PRCOM20131937, Building Permit - Commercial Address: 228 NW OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling John Borns Partial Friday, February 14, 2014

Inspection

Partial Correction

1 MISC OK TO COVER WHEN READY GWB CEILING FRAMING + ABOVE-CEILING

SYSTEMS @ FOLLOWING LOCATIONS: SOFFIT AT 116 W WALL; SOFFIT AT 115;

105; 107; 124; GWB CLOUD @ 103;

Partial Correction

2 MISC OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING

SYSTEMS @ FOLLOWING SPACES AFTER TEMPORARY WIRING IS REMOVED:

102-103; 106; 108; 110-111; 113-114; 116-119; 121-122; 127;

Comments: