PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRRES20131163, Building Permit - Residential

Address: 610 NW REDBUD DR, Unit:B, LEES SUMMIT, MO 64081610 NW REDBUD DR, Unit:A, LEES

SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Electrical Service John Borns Failed Friday, May 09, 2014

Inspection - Residential

Corrective Action Required

1 MISC NEC 250.92B; IRC E3510.1. BONDING OF SERVICE ENCLOSURES &

EQUIPMENT: NIPPLES ENTERING THROUGH REMAINING KNOCKOUTS
REQUIRE BONDING BUSHINGS WITH BONDING JUMPERS TERMINATED AT
ENCLOSURE HOUSINGS. LOCKNUT NOT SUFFICIENT FOR BONDING. MAY ALSO

RUN SEPARATE BONDING CONDUCTOR LUGGED TO ENCLOSURES.

Gas Service Inspection - John Borns Passed Friday, May 09, 2014

Residential

Comments: