PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20140191, Building Permit - Commercial Address: 901 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Failed Tuesday, May 20, 2014

Corrective Action Required

1 MISC SOUTH WALL @ 56' EAST END EXPANSION SPACE: NEC 300-11, 330.30 &

334-10 INSTALLATION OF MC ELECTRICAL CABLE: NOT SECURELY FASTENED

WITHIN 12" OF ENTRY TO BOXES. DO NOT COVER.

Corrective Action Required

2 MISC WALL IN-FILL @ EAST WALL NE CORNER: DRAWING CALLS FOR STEEL

FRAMING -- NOT WOOD. DO NOT COVER

Comments: