

# Temporary Certificate of Occupancy

---

**Permit #:** PRCOM20132180  
**Address:** 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086  
**Inspected On:** Thursday, May 29, 2014  
**Inspected By:** John Borns  
**Expiration Date:** 9/4/2014 12:00:00 AM

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Commercial</b>	John Borns	Temporary C of O	Thursday, May 29, 2014

Corrective Action Required:

1 MISC SOME FIRE DOORS DO NOT DISPLAY UL LABELS

Corrective Action Required:

2 MISC 18" VERTICAL SIDEWALL GRAB BARS MIS-LOCATED AT TOILET  
ROOMS 5A061A; 063; 133; 134

Corrective Action Required:

3 MISC TWO ELECT RECEPTS @ 5A136 WITHIN 6' OF EDGE OF SINK NEED  
TO BE GFCI PROTECTED.

Corrective Action Required:

4 MISC CRITICAL CIRCUIT ELECT RECEPTS @ IT 5A070 YET TO BE TESTED  
WHEN CIRCUITS ARE HOT