

CODES ADMINISTRATION

Temporary Certificate of Occupancy

Permit #: PRCOM20122455

Address: 1609 NW OBRIEN RD, LEES SUMMIT, MO 64081

Inspected On: Tuesday, July 15, 2014

Inspected By: John Borns

Expiration Date: 7/24/2014 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Temporary C of O Tuesday, July 15, 2014

Codes Commercial

Corrective Action Required:

1 MISC DOWNSPOUTS AND SPLASH BLOCKS / LEADERS NOT COMPLETED.

Corrective Action Required:

2 MISC ROOFS OVER E & W ENTRANCES NOT COMPLETED

Corrective Action Required:

5 MISC PERMANENT SIGNAGE SUBJECT TO APPROVAL WHEN IN PLACE:

- BUILDING STREET ADDRESS

- UNIT NUMBERS

Corrective Action Required:

6 MISC RESOLVE FIRE DEPARTMENT ISSUES.

Corrective Action Required:

7 MISC EXTERIOR SUBJECT TO APPROVAL WHEN COMPLETED.