
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20141829, Public Works Infrastructure Permit - Residential
Residences at New Longview
Address: 3301 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
PW-Sanitary Sewer Construction Inspection Corrective Action Required 1 Tied into manhole and laid two sticks out of manhole. Corrective Action Required 2 Laid from MH A3 to A4 Corrective Action Required 3 MH A4 to MH a5	Jon Haley	Partial	Tuesday, July 15, 2014
PW-Sanitary Sewer Construction Inspection Corrective Action Required 1 Tied into manhole and laid two sticks out of manhole. Corrective Action Required 2 Laid from MH A3 to A4	Jon Haley	Partial	Tuesday, July 15, 2014

Comments:
