

☐ **CHANGES**

BUSINESS NAME	TUESDAY MORNING EXPANSION		
ADDRESS	901 NW OBRIEN RD, LEES SUMMIT, MO 64081		
OWNER/OPERATOR NAME	LUKE DRAILY CONSTRUCTION:	TELEPHONE	(816) 459-8531
ADDRESS	75 NW BUSINESS PARK LN RIVERSIDE, MO 64150 Primary: (816) 459-8531 Cell: (816) 215-4059		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#: 195M	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM10240191

LOSS REDUCTION NARRATIVE

☐ **NO VIOLATIONS NOTED**

☐ **ALL VIOLATIONS RESOLVED**

Last Inspection

1st Inspection

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Thursday, June 19, 2014
Corrective Action Required: 1 - address front and rear doors of new area as "901" - mount one 2A-10BC fire extinguisher at the front entrance and rear exit - rated storage area must be constructed before separation wall is taken down.			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
June 19, 2014	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	