

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFR20141829, Public Works Infrastructure Permit - Residential  
Residences at New Longview  
Address: 3301 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

**Inspection Item:**

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
PW-Site Visit	Jon Haley	Partial	Friday, September 26, 2014

**Corrective Action Required**

1 A water truck is needed to keep dirt and dust from leaving your site. All attempts should be made to keep this from happening.

**Corrective Action Required**

2 Went and looked at domestic water meter vault. 3" water line, told the contractor i would psi test the line and pull bac t samples. But mark would continue to look at construction of the line.

**Corrective Action Required**

3 Spoke with contractor about testing and water shut down. Went over about the next two weeks plans.

**Comments:**