



CHANGES

<b>BUSINESS NAME</b>	SAINT LUKES EAST - MRI #2		
<b>ADDRESS</b>	20 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086		
<b>OWNER/OPERATOR NAME</b>	MCCARTHY BUILDING COMPANIES INC:	<b>TELEPHONE</b>	(913) 202-7002
<b>ADDRESS</b>	10601 MISSION RD SUITE 220 LEAWOOD, KS 66206 Primary: (913) 202-7002 Cell: <NO CELL PHONE>		

**EMERGENCY CONTACT INFORMATION**

NAME	TELEPHONE
1.	
2.	
3.	
4.	

**LOSS REDUCTION TYPE**

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
<b>CLASS:</b> I-1	<b>Map#:</b> 175X	<b>PFA#:</b>	<b>KNOX BOX:</b>	<b>KNOX LOCATION:</b>	<b>PERMIT #</b> prcom20142405

**LOSS REDUCTION NARRATIVE**

NO VIOLATIONS NOTED

ALL VIOLATIONS RESOLVED

Last Inspection      1st Inspection      2nd Inspection      3rd Inspection      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
<b>Occupancy Inspection - Fire</b>	Joe Dir	Temporary C of O	Thursday, October 16, 2014
Corrective Action Required:			
1	-storage room IC221 - permanently locate the alarm notification device in the corridor -breakroom C183A make sure the smoke detector in the breakroom is secured in the ceiling once the ceiling tile is replaced - if room IC221 is to be used for storage then the room has to be a 1-hour rated room - install properly rated doors in the rest room doorways		
<b>Alarm Test</b>	Joe Dir	Passed	Tuesday, October 14, 2014

<b>DATE OF REPORT</b>	<b>INSPECTOR</b>	<b>PREVENTION FOLLOW-UP REQUIRED?</b>	<b>RESPONSIBLE SIGNATURE</b>
-----------------------	------------------	---------------------------------------	------------------------------

October 16, 2014

Joe Dir

Yes

No