

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20142582, Building Permit - Commercial
Address: 500 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Final Building Inspection - Commercial	John Borns	Failed	Monday, December 29, 2014

Corrective Action Required

1 Misc 1

ENSURE CIRCUIT LABELS AT ELECTRICAL PANEL ARE COMPLETE, ACCURATE AND CURRENT. SEE POSITIONS 6/8.

Corrective Action Required

2 Misc 1

NEC 370-20; IRC E3806.5-6 SET-BACK OF ELECTRICAL RECEPTACLE / SWITCH BOXES: 1/4" MAXIMUM SET-BACK @ NON-COMBUSTIBLE SURFACES. SEE AT KITCHEN BACKSPLASH.

Corrective Action Required

3 Misc 1

NEC 380-10; 410-56(f) / IRC E3901.10; E3902.6 SECURING OF ELECTRICAL RECEPTACLES / SWITCHES: SOME NOT TIGHT TO BOX; CHECK ALL AND ENSURE NONE ARE "SOFT" OR LOOSE SIDE-TO-SIDE. SEE ABOVE BREAK ROOM COUNTER AND ELSEWHERE.

Corrective Action Required

4 Misc 1

BREAK AREA:

- OPEN DRAIN LINE FITTING?
- CHECK SLOPE OF CONNECTED DRAIN LINE. CORRECT IF NOT POSITIVE.
- SECURE WATER LINE TERMINATIONS AT VANITY
- IRC P2717.3 BACKFLOW PREVENTION AT DISHWASHER: DRAIN DISCHARGE LINE MUST RISE TO UNDERSIDE OF COUNTER AND BE SECURELY FASTENED (OR APPROVED ALTERNATE MEANS TO MAINTAIN HIGH POINT IN DISCHARGE LINE.)

Corrective Action Required

5 Misc 1

OCCUPANCY STATUS: IF APPROVED BY FIRE DEPARTMENT OK TO SET UP FOR BUSINESS. NO PUBLIC PRIOR TO APPROVAL.

Comments: