

PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #: PRRES20143054, Building Permit - Residential  
Address: 4350 SW PRYOR RD, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Electrical Service Inspection - Residential</b>	Mark Harding	Failed	Tuesday, January 20, 2015

Corrective Action Required

1	Misc 1	ground panels to water service
---	--------	--------------------------------

<b>All Rough Inspection - Residential</b>	Mark Harding	Failed	Tuesday, January 20, 2015
---	--------------	--------	---------------------------

Corrective Action Required

1	Misc 1	<ul style="list-style-type: none"><li>- firestop basement walls vertical to horizontal and every 10 horizontal, bath room, bedroom, all required locations</li><li>- 1/2 plywood used as firestop 3/4" required</li><li>- sub panel not installed in furnace room?</li><li>- solid block over joists and bearing locations on all joist</li><li>- strap garage door headers to top plates, braced wall requirement</li><li>- plate bolts rear basement wall at door and garage door.</li><li>- ground panel to water line</li></ul> ok to insulate do not cover inspection items.
---	--------	---

<b>Gas Service Inspection - Residential</b>	Mark Harding	Failed	Tuesday, January 20, 2015
---	--------------	--------	---------------------------

Corrective Action Required

1	Misc 1	fireplace not installed - recall when fireplace and flue is set. 2nd inspection- install gas lines to fireplaces pressure is ok
---	--------	---

**Comments:**

