

PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #: PRCOM20141078, Building Permit - Commercial  
Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Mark Harding	Partial	Thursday, April 30, 2015

Corrective Action Required

1	FIRST FLOOR	1ST LAYER
---	-------------	-----------

Corrective Action Required

2	SECOND FLOOR	CORRIDOR-1ST OK 2ND LAYER AT 2HR WALLS EXTERIOR SIDE  IT ROOM FAILED
---	--------------	---

Corrective Action Required

3	THIRD FLOOR	2ND LAYER AT 2HR WALLS EXTERIOR SIDE  SOUTH STAIRS- 2ND LAYER OK
---	-------------	--

Corrective Action Required

4	FOURTH FLOOR	CORRIDOR 1,2, OK CAULK GAPS ON 2ND ROOMS -  1ST LAYER STAIR WALLS ABOVE 4TH FLOOR -1ST LAYER STAIRS CEILING - -
---	--------------	---

Corrective Action Required

5	LOWER LEVEL	RATED CEILING - 2ND LAYER OK , EXCEPT OUTSIDE IT ROOM. EAST END OF CORRIDOR NEEDS SHEETROCKED WHEN PIPES ARE DROPPED FROM CEILING.
---	-------------	---

ALCOVES IN CORRIDOR NEEDS 1ST LAYER  
(INSTALLED CHANNEL ON CEILINGS NEEDS REMOVED)

Corrective Action Required

6

Misc 1

1ST FLOOR CORRIDOR OK, "D" UNIT OK

2ND FLOOR IT ROOM 6" DUCT TO FLOOR SPACE NEEDS FIXED

2ND FLOOR "D" UNIT 3RD FLOOR CAULK PLUMBING LINES TO FLOOR SPACE

3RD FLOOR OK

4TH DRYER VENTS ok

**Comments:**