

PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #: PRCOM20141078, Building Permit - Commercial  
Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Mark Harding	Partial	Wednesday, May 06, 2015

Corrective Action Required

1 FIRST FLOOR 1ST LAYER

Corrective Action Required

2 SECOND FLOOR  
CORRIDOR-1ST OK  
2ND LAYER AT 2HR WALLS EXTERIOR SIDE  
  
IT ROOM FAILED

Corrective Action Required

3 THIRD FLOOR  
2ND LAYER AT 2HR WALLS EXTERIOR SIDE  
  
SOUTH STAIRS- 2ND LAYER OK

Corrective Action Required

4 FOURTH FLOOR  
CORRIDOR  
1,2, OK  
CAULK GAPS ON 2ND  
ROOMS -  
  
1ST LAYER STAIR WALLS ABOVE 4TH FLOOR  
-1ST LAYER STAIRS CEILING  
-  
-

Corrective Action Required

5 LOWER LEVEL  
RATED CEILING - 2ND LAYER OK , EXCEPT OUTSIDE IT ROOM.  
EAST END OF CORRIDOR NEEDS SHEETROCKED WHEN PIPES ARE DROPE  
D FROM CEILING.

ALCOVES IN CORRIDOR NEEDS 1ST LAYER  
(INSTALLED CHANNEL ON CEILINGS NEEDS REMOVED)

**Corrective Action Required**

6 Misc 1

1ST FLOOR CORRIDOR OK, "D" UNIT OK  
2ND FLOOR IT ROOM 6" DUCT TO FLOOR SPACE NEEDS FIXED  
2ND FLOOR "D" UNIT 3RD FLOOR CAULK PLUMBING LINES TO FLOOR SPACE  
3RD FLOOR OK  
4TH DRYER VENTS ok  
BSMT - 1ST OF 2HR WALLS  
3RD OF 4 AT EAST STAIR TOWER  
4-WEST,3RD EAST TOWER  
IT ROOMS 2ND

**Comments:**