PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Above Ceiling Mark Harding Not Ready Monday, May 11, 2015

Inspection

Corrective Action Required

1 LOWER LEVEL GARAGE - CORRIDOR

-SPRINKLER PIPING SCREWED TO FLOOR JOIST NEED TO MOVE OR LOWER

FOR ROCK

**.--OK TO ROCK 2ND LAYER UPTHI THIS POINT OUTSIDE UNIT#5 STORAGE.

- EAST END :WATER PIPING, 3" DWV , AGAINST FLOOR JOIST REMOVE TO

INSTALL ROCK

OR PROVIDE APPROVED FIRE COLLARS AND LISTING FOR INSPECTION.

Corrective Action Required

2 FIRST FLOOR HARD LID-

CORRIDOR, 1ST LAYER OK

Corrective Action Required

3 SECOND FLOOR CORRIDOR OR TO ROCK CEILING

Corrective Action Required

4 THIRD FLOOR CORRIDOR OR TO ROCK CEILING

Corrective Action Required

5 FIRST FLOOR CORRIDOR OR TO ROCK CEILING-

UNIT CEILING - OK TO ROCK RIBBON STRIP FOR DUCTS WHERE DROP

CEILING ARE.

Corrective Action Required

6 THE FOLLOWING AREAS not ready for inspection all floors for above ceiling corridor-above ceiling.

ARE APPROVED

1st 2nd 3dr

4th

ground

Rated Assembly Inspection	Mark Harding	Partial	Monday, May 11, 2015
Partial Correction			
1 Misc 1	-2nd LAYER LOWER LEVEL CORRIDOR CEILING SCREW ONLY		
	-2ND LAYER SCREW LOWER LEVEL CORRIDOR WALLS		
	-GARAGES 1,2,3 FIRST LAYER APPROVED		
	-2ND LAYER LOWER LEVEL 2 HOUR CONDITONS ROOMS		
	- EAST AND WEST TOWER 4TH FLOOR 4TH LAYER LID APPROVED -WALLS BETWEEN UNITS ONLY 4TH FLOOR		
	elevator equipment room		
Partial Correction			
2 Misc 1	WAL	LS & CEILINGS @	1ST FLR STORAGE ROOMS:
	GWB OK TO TAPE, MUD AND FIRE-SEAL. ALL FIRE SEALING AND FIRE		
		•	IPE, ETC SUBJECT TO APPROVAL.

Comments: