PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Above Ceiling Inspection		Mark Hardi	ng Partial	Monday, May 18, 2015	
Corrective Action Required 1 LOWER LEVEL		GARAGE - CORRIDOR north stair replace rock where sprinkler line was moved caulk all penetrartions in corridor ceiling			
Corrective Action Required 2 FIRST FLOOR			D" unit ok to cover ceiling		
Corrective Action Required 3 SECOND FLOOR		CORRIDOR ceiling failed holes cut in both layers			
			holes cut in D unit ceiling		
Corrective Action Required 4 THIRD FLOOR		3rd floor corridor ok to rock D unit ok to cover			
		a d			
5	re Action Require FOURTH FLOO		CORRIDOR OR TO ROCK CEILI UNIT CEILING - OK TO ROCK F CEILING ARE. provide listing on 6" duct for p provide damper each side of c	BIBBON STRIP FOR DUCTS WHERE DROP	
Correctiv	e Action Require	ed			
6	Misc 1				

SALLY SARVADI 05/18/2015 8:07 AM

Comments: