
PLANNING AND DEVELOPMENT**Final Inspection Report**
Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial**Permit Project Title:** RESIDENCES AT NEW LONGVIEW**Address:** 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Planning	Hector Soto, Planner	Temporary C of O	Thursday, June 11, 2015

Corrective Action Required

1

LANDSCAPING. Complete landscaping per the approved landscape plan.

Corrective Action Required

2

MISCELLANEOUS EXTERIOR WORK.

- The building's stone base shall be completed per the approved building elevations. The remaining side left to be completed is on the west building elevation. Completion of the work was in process at the time of inspection.
- Installation of rain gutters was in the process of being completed on the north building elevation at the time of inspection.
- Broken windows were in the process of being replaced at the time of inspection.

Comments: