PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141079, Building Permit - Commercial Address: 3361 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Mark Harding Partial Wednesday, June 17, 2015

Inspection

Corrective Action Required

4 SECOND FLOOR 2ND FLOOR UNITS;

Corrective Action Required
3 THIRD FLOOR
Corrective Action Required

2 FOURTH FLOOR 1ST LAYER 4TH FLOOR CEILING;

Corrective Action Required

1 THE FOLLOWING AREAS -ELEVATORWALL 1-4

ARE APPROVED -ELEVATOR CEILING -1,2,3-TRACK
2HR RATED WALL- STAIR WALLS-

2HR RATED WALL- STAIR WALLS-ROOM SIDE :1STLAYER OK-1-4

;2ND LAYER OK1-4

-STAIR TOWER 1ST LAYER 1-4 TOWER CEILING 1ST LAYER

CORRIDORS-1-4 1ST LAYER

6-12,

CORRIDOR CEILINGS 2ND LAYER

2HR STAIR WALL HALL SIDE 1ST LAYER1-3

CORRIDOR WALLS -1-4

ROOMS-1ST FLOOR

All Rough Inspection - Mark Harding Partial Wednesday, June 17, 2015 **Commercial**

Corrective Action Required

1 FIRST FLOOR UNITS-ONLY

GARAGE ROUGH INSPECTION
HOLD DOWNS CLEAN OUTS CAULK-PENDING RE-INSPECTION

6/17

-CAULK ROOF DRAINS AT PLATE LINE

-JOIST BLOCKING BEARING WALL- ADD BLOCK ON ONE SIDE OF TRUSS

-ELEVATOR ROOM, CUT JOSIT FOR DRAIN

-G6, SPRINKLER VALVE

-HVAC CORRIDOR, 2LAYERS OF ROCK COMPROMISEDFOR HVAC THROUGH

WALL

-CAULK ROOF DRAIN G7

G8- CLEAN OUT G8 ANCOR BOLTS

RISER ROOM- DRILLED STUDS FOR MAIN WATER LINE.

Corrective Action Required

2 SECOND FLOOR COMPLETE

Corrective Action Required

3 THIRD FLOOR COMPLETE

Corrective Action Required

4 FOURTH FLOOR HVAC- DROPS 4TH FLOOR INSPECTION

Comments: