PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20150837, Building Permit - Commercial Address: 1174 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Occupancy Inspection - John Borns Not Ready Thursday, June 18, 2015

Codes Commercial

Corrective Action Required

1 Misc 1 RESOLVE FIRE DEPT ISSUES

Corrective Action Required

2 Misc 1 REAR (WEST) AREA SPACES NOT READY FOR FINAL INSPECTION. FINISH

PLUMBING IN PROGRESS. NOT ALL CIRCUITS HOT.

Corrective Action Required

3 Misc 1 FINISH ELECTRICAL TO BE COMPLETED AT NE CORNER

Corrective Action Required

4 Misc 1 ONE MC CABLE RUN TO BE SUPPORTED ABOVE CEILING GRID ABOVE

CHARTING AREA.

Corrective Action Required

5 Misc 1 LIGHT FIXTURE AT BREAK/UTILITY ROOM OBSTRUCTED BY NEW WALL.

Corrective Action Required

6 Misc 1 WALLS AT RESTROOMS, IF PAINTED, MUST BE EPOXY PAINT FOR

NON-ABSORBENCY.

Corrective Action Required

7 Misc 1 INSTALL SPARK RINGS AT RESTROOM ELECTRICAL RECEPTACLES TO CORRECT

EXCESSIVE SET-BACK AND TO MAKE DEVICES SECURE.

Corrective Action Required

8 Misc 1 VERTICAL SIDEWALL GRAB BARS IN RESTROOM MUST BE 39" TO 41" FROM

REAR WALL AND 39" TO 41" FROM FLOOR TO BOTTOM POINT OF

ATTACHMENT.

Corrective Action Required

9 Misc 1 NEC 110-22; 384-13; IRC E3606.2 LABELING OF ELECTRICAL CIRCUIT

BREAKERS: EACH BREAKER MUST BE LABELED WITH REFERENCE TO SPECIFIC SPACE(S) OR EQUIPMENT SERVED. MUST BE LEGIBLE; SPECIFIC. NO DITTO MARKS OR CONTINUATION SYMBOLS FOR INDIVIDUAL BREAKERS. LABEL

UNUSED BREAKERS "SPARE"

Corrective Action Required

10 Misc 1 ICC 117.1 HANDICAPPED ACCESSIBLE RESTROOM SIGNS TO BE AFFIXED AT

RESTROOMS

Comments: