

Inspection Summary

Permit #: PRCOM20141080, Building Permit - Commercial

Address: 3371 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Failed	Wednesday, June 24, 2015

Corrective Action Required

1	FIRST FLOOR	ELEVATOR - 1ST LAYER MISSING SCREWS ON STUDS 16" O.C. STAIRS- MISSING SCREWS 3RD FLOOR, AND 16" O.C. STUD WALLS
---	-------------	--

Rated Assembly Inspection	Mark Harding	Partial	Wednesday, June 24, 2015
----------------------------------	--------------	---------	--------------------------

Comments: